




1. Untie the cap




2. Insert the part onto the base




3. Connect wires



4. Apply the cap by rotating



5. Apply screws to make it stable



6. Plug it in the power