



1




Turn off the general switch

2




Mark & drill holes
Apply plastic anchors & tie up screws

3




Connect wires

4



Fix the mask in place

5



Turn on the general switch

